

To: Chairperson and Public Safety and Transportation Committee

From: Matthew Lew, PE, Civil Engineer W

Through: Carl Goldsmith, Director of Public Works

Date: October 27, 2015

Subject: November 2015 Meeting Item 2—2015 Replacement Yield Signs

near Hammerschmidt Elementary School


The Committee requested staff to determine 2015 replacement needs for Yield signs by Hammerschmidt Elementary School at the below intersections.

• Harrison Rd at Norbury Ave, West Circle Ave, East Circle Ave /Lombard Ave, LaLonde Ave

Harding Rd at LaLonde Ave

The intersections are shown with blue circles in the below exhibit with existing intersection control. All intersections were reviewed for stop signs. Per MUTCD Sections 2B.04 and 2B.06, these intersections do not meet the required conditions for Stop signage. Unlike Stop signs, Yield signs do not have specific conditions for installation except that such signage should not be used for speed control. Removing such signage may present Village liability concerns for potential future incidents. Such policy has been reviewed and recommended by Public Works staff. Since all intersections have existing signage and do not meet stop sign conditions, the Village recommends retaining the Yield signs as shown for this and future intersection replacement.

Staff recommends no changes to the intersection signage.



Stop and Yield Signage by Hammerschmidt School