


VILLAGE OF LOMBARD
REQUEST FOR BOARD OF TRUSTEES ACTION
For Inclusion on Board Agenda
Bids and Proposals

TO : President and Village Board of Trustees
FROM : Scott Niehaus, Village Manager
DATE : April 27, 2022 Agenda Date: May 5, 2022
TITLE : 100' Ladder Tower Unit FS52 Emergency Repair
SUBMITTED BY: Tom Ellis, Operations Superintendent 

RESULTS:

Date Bids Were Published N/A Bidding Closed N/A
Total Number of Bids Received 1
Total Number of Bidders Meeting Specifications 1
Bid Security Required Yes X No
Performance Bond Required Yes X No
Were Any Bids Withdrawn Yes X No
Explanation:
Waiver of Bids Requested? X Yes No
If yes, explain:
See attached memo.
Award Recommended to Lowest Responsible Bidder? X Yes No
If no, explain: **See attached memo.**

FISCAL IMPACT:

Amount of Award FY22 \$31,985.00, 610.270.345.75750

BACKGROUND/RECOMMENDATION:

See attached memo.

Has Recommended Bidder Worked for Village Previously X Yes No
If yes, was quality of work acceptable X Yes No
Was item bid in accordance with Public Act 85-1295? Yes X No
Waiver of bids - Public Act 85-1295 does not apply X Yes

REVIEW (as needed):

Village Attorney XX _____ Date _____
Finance Director XX _____ Date _____
Village Manager XX _____ Date _____

NOTE: All materials must be submitted to and approved by the Village Manager's Office by 12:00 noon, Wednesday, prior to the Board Agenda distribution.



Memorandum

To: Scott Niehaus, Village Manager

Through: Carl Goldsmith, Director of Public Works *CG*

From: Tom Ellis, Operations Superintendent *TE*

Date: April 27, 2022

Subject: Emergency Repair, Ladder tower FS52

Staff contacted Underwriters Laboratory (UL) to conduct the NFPA Apparatus Aerial Inspection for unit FS52, 100' aerial ladder tower. During the inspection on 3/16/22, several corrective items were identified by the inspector for immediate attention. There were some minor mechanical items that have been repaired by staff. The inspector identified several areas of corrosion (rust) on key components of the ladder tower and a dent on a main structural component of the ladder assembly. The inspector has given the Village 90 days to complete the repairs that were identified before having to start the inspection process over again.

Due to dent being on a structural component of the ladder assembly, the manufacturer had to conduct a structural engineering appraisal for the dented area to ensure the internal integrity of the structural component and that it could be repaired without effecting the ladder certification. After a review, the manufacture has determined that the dent may be repaired and refered staff to Chandler Services, Inc of Mokena IL. Chandler is familiar with the manufacture's specifications for repairing a dent in a structural member of the ladder assemble.

Staff contacted Chandler Services and scheduled FS52 to have the Ladder repaired and have Chandler address the corrosion areas identified by the UL inspector and maintain the 90 day deadline to avoid having to start a new inspection process.

Staff is recommending the approval of the emergency repairs to Chandler Services, Inc. Mokena, Il in an amount not to exceed \$31,985.00.

Please place this item for consideration on the May 5, 2022 Board agenda.



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002417	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44
Address:	50 E ST CHARLES RD	VIN:	4P1CD01H67A007651
City/State/Zip:	LOMBARD, IL 60418	Style:	
Phone:	- -	Plate/State:	-
Cell Phone:	- -	WMI:	FIN:
Purchase Order:		Odometer:	
Customer Number:	014940002417	Color:	
Claim Contact:		Date Of Loss:	
Contact Title:		Authorized By:	
Contact Phone:	x	Claim Number:	
Contact Email:		RO:	JOB#19346

Operation	Description	Part #	Type	Labor	Paint	-----Parts-----	Misc
----- AERIAL PLATFORM -----							
1	^ Replace	SANDBLAST CYLINDERS	New	3.00	5.00		\$300.00
2	^	REMOVE CONCRETE GRIP		10.00			
3	* Repair	SANDBLAST PLATFORM			25.00		\$1,000.00
4	^ R&I	CONTROL TOWER		7.00			
5	^ R&I	RAILINGS		6.00			
----- LADDER -----							
6	* Repair	SANDBLAST LADDER SECTIONS			19.00		\$500.00
7	^ R&I	REMOVE MISC COMPONENTS		4.00			
8	^ Repair	REPAIR DENT IN LADDER	F	8.00			
----- Custom Services -----							
9		Prep For Delivery	CS	2.00			\$20.00
----- Calculated Values -----							
10	^	Shop Supplies	Mtrls				\$399.00
11	^	Hazardous Waste					\$15.00
12	^	Truck Cover	Mtrls	2.00		@ \$68.00	\$0.00
13	^	Two stage paint.			14.80		
14	^	Paint Materials	Mtrls				\$2,556.00

An '*' indicates user change of database part and '^' indicates manually entered or custom database rows.

Estimate Notes:



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002417	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44

Summary	Amount	Rate	Disc	Total
Body Labor	24.0	\$95.00	0.00%	\$2,280.00
Paint Labor	63.8	\$95.00	0.00%	\$6,061.00
Mechanical	0.0	\$115.00	0.00%	\$0.00
Frame	8.0	\$105.00	0.00%	\$840.00
Misc. Labor	10.0	\$95.00	0.00%	\$950.00
Parts	\$68.00		0.00%	\$68.00
Misc.				\$4,790.00
Sub-total				\$14,989.00
Sales Tax				0.00

Total				\$14,989.00
Betterment				\$0.00
Deductible				\$0.00
Grand Total				\$14,989.00



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date: 4/6/2022
Reference #: 014940002417
Estimated By: David Chandler
Name: LOMBARD FD

Year: 2007
Make: Pierce
Model: Dash
Unit #: T44



IMG_0904.JPG



IMG_0905.JPG



IMG_0906.JPG



IMG_0907.JPG



Chandler Services, Inc.

10203 W. 191st Street
Mokena, IL 60448

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date: 4/6/2022
Reference #: 014940002417
Estimated By: David Chandler
Name: LOMBARD FD

Year: 2007
Make: Pierce
Model: Dash
Unit #: T44



IMG_0908.JPG



IMG_0909.JPG



IMG_0910.JPG



IMG_0911.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@changerservicesinc.com Tax ID: 36-3070210

Date: 4/6/2022
Reference #: 014940002417
Estimated By: David Chandler
Name: LOMBARD FD

Year: 2007
Make: Pierce
Model: Dash
Unit #: T44



IMG_0912.JPG



IMG_0913.JPG



IMG_0914.JPG



IMG_0915.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date: 4/6/2022
Reference #: 014940002417
Estimated By: David Chandler
Name: LOMBARD FD


Year: 2007
Make: Pierce
Model: Dash
Unit #: T44



IMG_0916.JPG



IMG_0917.JPG



IMG_0918.JPG



IMG_0919.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandlerservicesinc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002417	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44



IMG_0920.JPG



IMG_0921.JPG



IMG_0922.JPG



IMG_0923.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204


Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date: 4/6/2022
Reference #: 014940002417
Estimated By: David Chandler
Name: LOMBARD FD

Year: 2007
Make: Pierce
Model: Dash
Unit #: T44



IMG_0924.JPG



IMG_0925.JPG



IMG_0926.JPG



IMG_0927.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204


Email: collision@changerservicesinc.com Tax ID: 36-3070210

Date: 4/6/2022
Reference #: 014940002417
Estimated By: David Chandler
Name: LOMBARD FD


Year: 2007
Make: Pierce
Model: Dash
Unit #: T44



IMG_0928.JPG



IMG_0929.JPG



IMG_0930.JPG



IMG_0931.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002417	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44



IMG_0932.JPG



IMG_0933.JPG



IMG_0934.JPG



IMG_0935.JPG



Chandler Services, Inc.

10203 W. 191st Street

Mokena, IL 60448


Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@changerservicesinc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002417	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44



IMG_0936.JPG



IMG_0937.JPG



IMG_0938.JPG



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002417	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44

TERMS & CONDITIONS

The above is an estimate based on inspection and does not cover additional parts or labor which may be required after the work has been started. Occasionally worn or damaged parts are discovered which may not have been evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

Signed _____ Date _____



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002418	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44
Address:	50 E ST CHARLES RD	VIN:	4P1CD01H67A007651
City/State/Zip:	LOMBARD, IL 60418	Style:	
Phone:	- -	Plate/State:	-
Cell Phone:	- -	WMI:	FIN:
Purchase Order:		Odometer:	
Customer Number:	014940002418	Color:	
Claim Contact:		Date Of Loss:	
Contact Title:		Authorized By:	
Contact Phone:	x	Claim Number:	
Contact Email:		RO:	JOB#19346

Operation	Description	Part #	Type	Labor	Paint	-----Parts-----	Misc
----- FRAME RAILS -----							
1	* Repair	SANDBLAST		15.00			\$5,400.00
2	* Repair	REFINISH RAILS AND OUTRIGGERS WITH DTM			50.00		
----- Custom Services -----							
3		Prep For Delivery	CS	2.00			\$75.00
----- Calculated Values -----							
4	^	Shop Supplies	Mtrls				\$180.50
5	^	Hazardous Waste					\$15.00
6	^	Truck Cover	Mtrls	2.00		@ \$68.00	\$0.00
7	^	Two stage paint.			18.00		
8	^	Paint Materials	Mtrls				\$2,992.50

An '*' indicates user change of database part and '^' indicates manually entered or custom database rows.

Estimate Notes:



Chandler Services, Inc.

**10203 W. 191st Street
Mokena, IL 60448**

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002418	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44

Summary	Amount	Rate	Disc	Total
Body Labor	19.0	\$95.00	0.00%	\$1,805.00
Paint Labor	68.0	\$95.00	0.00%	\$6,460.00
Mechanical	0.0	\$115.00	0.00%	\$0.00
Frame	0.0	\$105.00	0.00%	\$0.00
Misc. Labor	0.0	\$95.00	0.00%	\$0.00
Parts	\$68.00		0.00%	\$68.00
Misc.				\$8,663.00
Sub-total				\$16,996.00
Sales Tax				0.00

Total				\$16,996.00
Betterment				\$0.00
Deductible				\$0.00
Grand Total				\$16,996.00



Chandler Services, Inc.

10203 W. 191st Street

Mokena, IL 60448

Phone: (708) 478-4200 Fax: (708) 478-4204

Email: collision@chandler-services-inc.com Tax ID: 36-3070210

Date:	4/6/2022	Year:	2007
Reference #:	014940002418	Make:	Pierce
Estimated By:	David Chandler	Model:	Dash
Name:	LOMBARD FD	Unit #:	T44

TERMS & CONDITIONS

The above is an estimate based on inspection and does not cover additional parts or labor which may be required after the work has been started. Occasionally worn or damaged parts are discovered which may not have been evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

Signed _____ Date _____