Legistar: 090778

DISTRICT 4

VILLAGE OF LOMBARD REQUEST FOR BOARD OF TRUSTEES ACTION For Inclusion on Board Agenda

X	Resolution or Ordinance (Blue)Waiver of First Requested Recommendations of Boards, Commissions & Committees (Green) Other Business (Pink)
TO:	PRESIDENT AND BOARD OF TRUSTEES
FROM:	David A. Hulseberg, AICP, Village Manager
DATE:	December 2, 2009 (COW) (<u>B of T</u>) Date: January 7, 2010
TITLE:	Special Assessment 217B Change Order #3 (Final)
SUBMITTED BY:	David A. Dratnol, P.E., Village Engineer And
BACKGROUND/P	OLICY IMPLICATIONS:
Finalizing quantities	of work for the contract.
FISCAL IMPACT/	FUNDING SOURCE:
\$45,775.43 DECRE Project #: ST-09-01 SPS Project #: 0901 P.O. #: 062700	
Review (as necessar	y): Date
Finance Director X	Date
	Date
NOTE:	All materials must be submitted to and approved by the Village Manager's Office by 12:00 noon, Wednesday, prior to the Agenda

Distribution.

AGENDA.DOC

Legistar: 090778

InterOffice Memo



To: David Hulseberg, Village Manager

From: David A. Dratnol, P.E., Village Engineer Link

Through: Carl Goldsmith, Director of Public Works (1)

Date: December 2, 2009

Subject: Special Assessment 217B

Change Order #3 (Final)

Attached, please find Change Order # 3 for this project in the amount of net deduction of \$45,775.43. The change order represents final quantities to existing contract items and new pay items.

EXISTING PAY ITEMS: Existing pay items that increased or decreased by \$5,000 or more are summarized below.

- 1. PAY ITEMS RELATED TO UNDERGROUND UTILITY CONSTRUCTION: Final trench backfill (Pay Item 11) quantities for storm sewer construction and water service line relocation were agreed to at 227 CY over the current contract quantity (\$6,364.40). Hydrant extensions for both the Village of Lombard (Pay Item 64) and Illinois American Water hydrants (Pay Item 65) were under the initial estimated contract quantities - a net deduction of \$5,250 and \$13,200 respectively. Pay Item 68 was reduced by \$8,600.00 in part due to the overestimate of quantities and the number of non-functioning b-boxes that were encountered. The non-functioning boxes were replaced and the cost for replacing the non-functioning boxes will be reimbursed to the Village by Illinois American Water. Refer to FA10A to FA10N (items 123-136).
- 2. PAY ITEMS RELATED TO ROADWAY EXCAVATION & CONSTRUCTION: Final field measurements for the pay items for Topsoil (Pay Item 13), Sodding (Pay Item 18), Sidewalk (Pay Item 32) and Curb and Gutter (Pay Item 87) were all under the original contract quantity. The item (Pay Item 116) related to the earth excavation for the soil with a greater than 0 VOC reading was 190 cubic yards over the current contract quantity. Total cost of this work results in a decrease of \$24,568.00 for these pay items.

NEW PAY ITEMS: Items that have been added to the contract since the previous change order are summarized below.

1. **ILLINOIS AMERICAN WATER:** Listed below are pay items that will be reimbursed to the Village from Illinois American Water. They are related to Illinois American Water infrastructure that was either not properly located or functioning. One item was a watermain repair related to the installation of a new water service.

No.	Item	Quantity	Unit	Price	Total
123	723 E LeMoyne - Unmarked service	1	LS	\$1,055.99	\$1,055.99
124	602, 606 & 610 N. Edgewood unmarked services	1	LS	\$1,055.99	\$1,055.99
125	528 E. LeMoyne - B-Box not keyable	1	LS	\$628.91	\$628.91
126	602 E. LeMoyne - B-Box not keyable	1	LS	\$671.72	\$671.72
127	610 N. Vista - Cracked watermain	1	LS	\$604.00	\$604.00
128	601 & 605 N. Vista - B-Box not keyable	1	LS	\$1,500.80	\$1,500.80
129	601 N Vista - B-Box not keyable	1	LS	\$960.11	\$960.11
130	610 E. LeMoyne - B-Box not keyable	1	LS	\$452.18	\$452.18
131	642 E. LeMoyne - B-Box not keyable	1	LS	\$452.18	\$452.18
133	638 E. LeMoyne - B-Box not keyable	1	LS	\$562.55	\$562.55
134	641 N. Vista – B-Box not keyable	1	LS	\$631.20	\$631.20
135	635 N. Edgewood - B-Box not keyable	1	LS	\$198.58	\$198.58
136	651 N. Edgewood- B-Box not keyable	1	LS	\$198.58	\$198.58
· · · · · · · · · · · · · · · · · · ·	1	.1		Total	\$6,860.81

Legistar: 090778 Special Assessment 217B Change Order #3 (Final) Page 2 of 2

Listed below are pay items that are the Village of Lombard's responsibility and are not eligible for reimbursement under the agreement with Illinois American Water.

No.	Item	Quantity	Unit	Price	Total
132	626E LeMoyne - B-Box under paved driveway	1	LS	\$562.55	\$562.55
137	Joyce & LeMoyne - Adjustment of valve box to new grade	1	LS	\$578.38	\$578.38
138	536 E. LeMoyne - Lowering auxiliary water valve to new grade	1	LS	\$362.23	\$362.23
***				Total	\$1,503.16

2. MISCELLANEOUS ITEMS: Pay item 139 was generated due to a concern by Village staff that the sidewalk was proposed to be installed at too high of an elevation, therefore needlessly increasing the slope of the affected residential driveways. The framing for the sidewalk was removed and the proposed sidewalk was lowered and reframed. Cost for this work was \$702.32. Pay item 140 (\$493.32) was related to the construction of two separate cleanouts to sump pump connections. Two clean outs were relocated to property line as to delineate the future responsibility of the property owner and the Village. Pay item 141 was the removal of sidewalk that was installed at too high of a grade. This cost for this work will be addressed by the consulting engineer and the contractor. The Village will not incur any costs for the removal and replacement of the sidewalk that was installed at the incorrect elevation. Pay item 142 (\$130.07) was to change the covers of the cleanouts to a slotted cover from a solid cover, a revision to the standard. This will prevent a backup/connection failure to the system in the event of a blockage on either side of the cleanout.

Prior to the Board meeting the proposed Change Order will be presented to the Public Works Committee on December 8th and the Board of Local Improvements on December 10th.

If recommended by both committees, please present this change order to the President and Board of Trustees for their review and approval at their regular meeting on January 7, 2010. If approved, please have two (2) signed copies returned to Public Works-Engineering for further processing.

RESOLUTION R 10

A RESOLUTION AUTHORIZING A CHANGE ORDER INVOLVING A DECREASE IN THE DOLLAR AMOUNT OF THE CONTRACT OF \$10,000 OR MORE

WHEREAS, pursuant to Illinois Compiled Statutes, Chapter 720, Section 5/33E-9, units of local government are required to make specific findings prior to authorizing any change order relative to a contract which would increase or decrease the dollar amount of the contract by \$10,000 or more, or would extend or shorten the time in which the contract is to be completed by thirty days or more; and

WHEREAS, staff has presented and recommended the proposed Change Order No. 3 to the contract between the Village of Lombard and ALamp Concrete Contractors Inc. regarding Special Assessment 217B, as attached hereto as Exhibit "A" and made part hereof, to the Corporate Authorities of the Village of Lombard; and

WHEREAS, said change order attached hereto as Exhibit "A" would decrease the dollar amount of the contract by \$45,775.43

NOW, THEREFORE, BE IT RESOLVED BY THE PRESIDENT AND BOARD OF TRUSTEES OF THE VILLAGE OF LOMBARD, DU PAGE COUNTY, ILLINOIS, as follows:

SECTION 1: That after reviewing the explanation of staff as to the necessity of and reasons for the change order attached hereto as Exhibit "A", the President and Board of Trustees find as follows:

- A That the circumstances which necessitated said change order were not reasonably foreseeable at the time the contract was entered into.
- B. That the basis of the change order was not within the contemplation of the contract when the contract was signed.
- C. That it is in the best interests of the Village of Lombard to approve the change order in its proposed form.
- D. That to the extent that it may have been necessary to go to bid relative to the work contemplated by said change order, bidding is hereby specifically waived as to the change order work.

Resolution10 Page 2		
and Board of Trustees hereby approv	nade the findings set forth in Section 1 above, the ve the change order attached hereto as Exhibit "A and Village Clerk to execute said change order or	", and direct
Adopted this day of	<u> </u>	, 2010.
Ayes:		
Nays:	·	
Absent:		
Approved this day of		, 2010.
ATTEST:	William J. Mueller Village President	
Brigitte O'Brien Village Clerk		

VILLAGE OF LOMBARD CHANGE ORDER #3

PROJECT NAME: Special Assessment 217B	PROJECT NO.:	ST-09-01						
LOCATION: Joyce, Edgewood, LeMoyne & Vista	CHANGE ORDER:	3 (Final)						
CONTRACTOR: ALAMP Concrete Contractors	DATE:	11/23/2009						
DESCRIPTION OF CHANGE ORDER: Final balancing of co	ontract pay items (quantities).							
ORIGINAL CONTRACT AMOUNT:		[1] \$2,162,972.07						
TOTAL OF PREVIOUS AUTHORIZED CHANGE ORDERS	: CO #1 & CO#2	[2] \$271,095.45						
CURRENT CONTRACT AMOUNT: ([1]+[2])		[3] \$2,434,067.52						
PROPOSED CHANGE ORDER: (PENDING APPROVAL)		[4] (\$45,775.43)						
PROPOSED REVISED CONTRACT AMOUNT: (PENDING	3 APPROVAL) ([3]+[4])	[5] \$2,388,292.09						
NET OF ALL CHANGE ORDERS: (PENDING APPROVALE) TIME EXTENSION OR REDUCTION:	_) ([2]+[4])\$225,320.02	-						
TOTAL CONTRACT TIME:	194 Calendar Days	-						
BUDGET ESTIMATE:	\$3,083,137.60							
ENGINEER'S ESTIMATE:	\$3,152,390.63	-						
RECOMMENDED FOR ACCEPTANCE:								
Resident Engineer Date App	proved By: Director of Finance	Date						
D : /<\$1	oroved By: OK or 25%) Village Manager	Date						
Contractor Bate	proved By:							
Village Engineer Date	Village President	Date						
Director of Public Works Date	proved By: President BOLI	Date						
Assistant Director of Finance Date	Attest: Village Clerk	Date						

It is understood that as part of this change order that the Contractor agrees that all bonds, permits, insurance and guarantees are hereby extended to incorporate this Change Order.

Special Assessment 217B

11/23/2009

Final

ო

¢.0.3

	Current	Unit	Unit	Revised	DIFFERENCE	AMOUNT	Description
No.	Quantity		Price				
AND BACKELL ODI	1,863.70	CUYD	28.00	2,091.00		ľ	
- 5	17,610	SQ YD	2.00	13,298.00		8	
2 5	205	FOOT	8.00	202.00			Final Balancing
\neg	2,115	SQYD	1.00	563.00		- 1	
= {	15,495	SQYD	4.00	12,912.00	\rightarrow	\$ (10,332.00)	Field measurements reduced plan quantity
L.	4	EACH	150.00	00.9	_		300.00 Final Balancing
£ 8	11,095	SQYD	15.50	10,837.00			(3,999.00) Field measurements reduced plan quantity
77	1.110	GALLON	2.20	398.00		\$ (1,566.40)	Field conditions reduced plan quantity
23		NOT	1.00	1.43	(25.57)	\$ (25.57)	Field conditions reduced plan quantity
24	1.569	NOT	70.00	1,606.00	37.00	2,590.00	2,590.00 Final Balancing
22	1 264	NOT	72.00	1,288.00	24.00	1,728.00	Final Balancing
78	75	OX OX	8.00	70.00	<u> </u>	\$ (40.00)	Final Balancing
40600980 27 HMA SURF REM BUTT JT	120,130	C V	50.00	143.00	ı	(350.00)	Final Balancing
78	12 152	SO YO	0.01	0.00	_	\$ (121.52)	Pay Item Not used
	350	1 N	36.00	362.00	L.,	\$ 108.00	Final Balancing
90	37.680	2 12	3.50	35.434.00	1=	\$ (7,861.00)	Field measurements reduced plan quantity
42400430 32 PC CONC SIDEWALK 5 SP	107	L	25.00	88.00	╙	\$ (400.00)	Field measurements reduced plan quantity
	1000	2 5	00 0	4 392 00	322.00	2,898.00	2,898.00 Driveways beyond the ROW were increased due to grades
44000200 36 DRIVE PAVEMENT REM	4,070	3 5	00.0	308 00	╁	(96.00))) Final Balancing
44000500 37 COMB CURB GUTTER REM	430	5 2	3.00	330.00	-		
38	3,811	100	20.1	2 166 00	+-	-	_
50105225 39 PIPE CULVERT REM SPL	1,00.1		2000	23.00	4-		77
41	91	5 5	10.00	23.00			Day flow not used
_		<u> </u>	45.00	0.00		1	
	161	1001	00.006	0.00	-	1`	I Tell Heavilles Not used
	24	24 F00T	550.00	0.00	-	7	10,200.00 () Fig. 13 conditions address also present to
	29	EACH	70.00	23.00		1	Treid Collutions leaded plan quantity
3 2	28 [28 EACH	90.00	12.00	_		Field conditions reduced plan quantily
	87	EACH	200.00	44.00	(43.00)		(8,600.00)) Field conditions reduced plan quantity
3 0	1,456 FOOT	F00T	15.00	1,311.00	-	_	(Z,1/5,00) Final Balancing
	99	EACH	75.00	47.00			Field conditions reduced plan quantity
	21	EACH	100.00	14.00	-	- [Field conditions reduced plan quantity
0 0	7,922	FOOT	13.00	7,525.00	-		
SUBUSSION OF COMIS CORO (DC.) 2	36	FOOT	100.00	0.00	_		
3 2	255	EACH	10.00	41.00	(214.00)	2) Field conditions reduced plan quantity
5	51	EACH	150.00	49.00	(2.00)		(300,00) Final Balancing
7 6	108	FOOT	12.00	100.00	(8.00))) Final Balancing
8 8	115	F00T	23.00	2	(7.00)	1	
t g	9	EACH	1,040.00		1.00		Added per Village request (Edgewood)
_	6,853	FOOT	2.75	6,573.00	(280.00)	ļ	
818U3U3U3 98 UD 2#0 #0G XI DISE 1 1//	985	FOOT	3.50	Ψ,	99.00	``	Added per Village request (Sunset)
	673	FOOT	1.70	644.00	(29.00)		(49.30) Final Balancing
39 OD 1 I/Z (ONE) WILLIAM AND XI DI ISE 2	07	FOOT	10.00	59.00	(11.00)		(110.00) Final Balancing
100 000 000 000 001 2 404 11D 746 044 44G XI DISE 0	215	FOOT	10.00		(18.00)	١	
SAGONOGO ANOLTE & RKEII F FI FCT WK	7,142	FOOT	2.20		(78.00)		
2000000 102 117 & DIVINE ACCESS	2,500	TON	0.01	1,760.00	(740.00)		
ZOCOGOSO 100 AGG FOR LEWIT ACCESS	2,600	SQYD	30.00	2,740.00	140.00	4,2	
	20	LINS	1.00		(8.00)	ļ	
	23	EACH	300.00	12.00	(11.00)	ဗျ) Field conditions reduced plan quantity
440 DAIMAGE & LITH ITY STRUCTIRES TO BE RECONSTRUCTED	8	EACH	975.00	7.00	(1.00)		Final Balancing
+	10	EACH	150.00	00.00	(10.00)	\neg	
1	7,285.00	ζ	39.00		190.00	1	Field measurements increased plan quantity (lowering sidewalks)
110	3,035.30	ζ	39.00	3,129.00	93.70	\$ 3,654.30	3,654.30 Field Conditions increased quantitys
AUF4 11/ NEW & DIST ONS WALE							

Courant triangle Courangle Courang		Description		2,811.00 Field Conditions increased quantitys	(2,090.00) Field measurements reduced plan quantity	(805.00) Deducted length due to cracks and debris in pipe	1.055.99 Illinois American Water Work	Illinois American Water Work	628.91 Illinois American Water Work	671.72 Illinois American Water Work	604.00 Illinois American Water Work	,500.80 Illinois American Water Work	960.11 Illinois American Water Work	Illinois American Water Work		Illinoin American Mater Mork		Illinois American Water Work	631.20 Illinois American Water Work	198.58 Illinois American Water Work	Illinois American Water Work	Illinois American Water Work	362.23 Illinois American Water Work	702.32 Change requested by Village staff	493.32 Change requested by Village staff	Cost paid by Consultant Engineer (due to layout error)	130 07 Change requested by Village staff	
Current Unit Revised DIFFERENCE	11/23/2009	AMOUNT	- 1									Γ																
Co. # 3 Final	.,	DIFFERENCE		93.70	(440.00)	(230.00)	100	1.00	1.00	1.00	1.00	1.00	1.00	1.00	100	60.	00.1	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	0.00	1 00	9:
Nat	Final	\vdash	Quantity	3,129.00	9,333.00	1 570.00	1 00	8 8	1.8	9.	100	1.00	100	100	5	3 5	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	100	1 00	5	3
Item Current Quantity Quantity 3,035.30 WAT B 4 3,035.30 3,035.30 Ork 723 Lemoyne (find taps unmarked service) 0 0,077.30 0,077.31 Lemoyne (find taps unmarked service) 0 0,077.32 Lemoyne (find taps unmarked service) 0 0,077.32 Lemoyne (find taps unmarked service) 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0 0,077.32 Lemoyne b-box un-keyable & replaced 0 0 0 0 0 0 0 0 0	ო	Unit	Price	30.00	4.75	3.50	1 055 99	1,000.33	628.91	671.72	604 00	1 500.80	960 11	452.18	450 48	452.10	562.55	562.55	631.20	198.58	198.58	578.38	362.23	702.32	493.32	1 216 55	70.004	130.07
Item Quan MAT B 4 Be storm sewer Ork 723 Lemoyne (find taps unmarked service) Ork 602,606, & 610 Edgewood (find taps unmarked service) Ork 602,606, & 610 Edgewood (find taps unmarked service) Ork 602 Lemoyne b-box un-keyable & replaced Ork 602 Lemoyne b-box un-keyable & replaced Ork 601 Vista water main cracked turning the corp (repaired) Ork 601 Vista b-box un-keyable & replaced Ork 601 Usta b-box un-keyable & replaced Ork 610 Lemoyne b-box un-keyable & replaced Ork 610 Lemoyne b-box un-keyable & replaced Ork 620 Lemoyne b-box un-keyable & replaced Ork 631 Emoyne b-box un-keyable & replaced Ork 632 Lemoyne b-box un-keyable & replaced Ork 633 Lemoyne b-box un-keyable & replaced Ork 634 Lemoyne b-box un-keyable & replaced Ork 635 Lemoyne b-box un-keyable & replaced Ork 636 Lemoyne b-box un-keyable & replaced Ork 637 Edgewood b-box broken replaced top Ork 636 Edgewood b-box broken replaced top Ork 636 Edgewood b-box broken replaced top Ork 637 Edgewood b-box broken replaced top Ork 638 Edgewood b-box broken replaced top Ork 637 Edgewood b-box broken replaced top Ork 638 Edgewood b-box broken replaced top Ork 639 Edgewood b-box broken replaced top Ork 640 Edgewood b-box broken replaced top Ork 651 Edgewood b-box broken replaced Ork 652 Edgewood b-box broken replaced Ork 654 Edgewood b-box brok	C.O. #	Unit		≿	λS	1	1	3 2	S	S	10	3	2	27	3 2	3	ST	rs T	ST	S	S	S	SI	S	2	2 0		
Item MAT B 4 he storm sewer fork 723 Lemoyne (find taps unmarked service) fork 602,606, & 610 Edgewood (find taps unmarked service) fork 602 Lemoyne b-box un-keyable & replaced fork 602 Lemoyne b-box un-keyable & replaced fork 602 Lemoyne b-box un-keyable & replaced fork 601 Usta water main cracked turning the corp (repaired) fork 603 and 605 Vista b-box un-keyable & replaced fork 601 Usta b-box un-keyable & replaced fork 601 Lemoyne b-box un-keyable & replaced fork 601 Lemoyne b-box un-keyable & replaced fork 632 Lemoyne b-box un-keyable & replaced fork 632 Lemoyne b-box un-keyable & replaced fork 633 Lemoyne b-box un-keyable & replaced fork 634 Lemoyne b-box un-keyable & replaced fork 635 Edgewood b-box un-keyable & replaced fork 636 Lemoyne b-box un-keyable & replaced fork 637 Lemoyne b-box un-keyable & replaced fork 638 Lemoyne b-box un-keyable & replaced fork 641 Lemoyne b-box un-keyable & replaced fork 641 Lemoyne b-box un-keyable & replaced for		Current	Quantity	3.035.30	9 773 00	4 800	000,-									0	0	0	0	0								-
	Special Assessment 217B			\neg	Т	_	AUP9 122 Televising the storm sewer	FA10A 123 IL. Amer. Work 723 Lemoyne (find taps unmarked service)	(10B 124 II. Amer. Work 602,606, & 610 Edgewood (Info tabs unintarked service)	(10C 125 II., Amer. Work 528 Lemoyne b-box un-keyable & leplaced	(10D 126 IL. Amer. Work 602 Lemoyne b-box un-keyable & leplaceu	FA10E 127 IL. Amer. Work 610 Vista water main cracked furning the colp (repaired)	110F 128 III., Amer. Work 609 and 605 Vista b-box un-keyable & replaced	(10G 129 IL. Amer. Work 601 Vista b-box un-keyable (debris) & replaced	FA10H 130 IL. Amer. Work 610 Lemoyne b-box un-keyable & replaced	FA10I 131 IL. Amer. Work 642 Lemoyne b-box un-keyable & replaced	132 II. Amer. Work 626 Lemoyne b-box in driveway un-keyable & replaced	400 11 Amor Work 638 Lemovne b-hox III-kevahle & replaced	FATUR 133 IL. Allie. Woln 030 Lellioyile B box all helphase a replaced	110L 1134 IL. Amer. Work 641 Vista D-box uit-keyable & lepiaceu	(10M 135 IL. Amer. Work 635 Edgewood b-box broken replaced top	136 IL. Amer. Work 651 Edgewood D-box Drokell replaced top	(100 137 Joyce and Leymoyne K & K valve box grade adjusterment	(10P 138 536 Lemoyne - Iower aux valve to grade	FA-11 139 Vista - Reframe sidewalk as requested	A-12 140 Edgewood Ave #655 & #643-relocate sump drain clear outs		142 Change cleanout for sump pump covers from solid lid to slotted lid as requested

TOTAL \$ (45,775.43)