

2015

GENERAL INFORMATION

Street Number: 137

Former Street Number: -

Street: South 3rd Avenue

PIN Number: 06-09-111-041

Construction Date (s): 1960

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached carport

Secondary Condition: Excellent

Secondary Integrity: Excellent

Alterations:

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: Yes

National Register Criterion: C

LHS Plaque: No LHC Landmark: No

Reason for Significance:

Excellent example of the Mid-Century Modern style with excellent integrity



ARCHITECTURAL DESCRIPTIONS

Architectural Style: Mid-Century Modern

Building Form: Ranch No. of Stories: 1

Current Wall Materials: Wood

Original Wall Materials: Wood

Ornamentation: Trellis

Storefront Materials: -

Roof Type: Flat Materials: -

Roof Ornamentation: Trellis

Foundation Material: -

Porch Type: Partial front

Door Detailing: Transom

Window Type: Fixed

Window Configuration: Banded

Window Material: Wood

Window Detailing: -

Significant Features:

Overhanging roof eaves with open trellis



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

NOTES

There is no current research on the house, which appears to have been built about 1960.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 206

Former Street Number:

Street: South Craig Place

PIN Number: 06-08-123-016

Construction Date (s): c. 1900

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Good

Secondary Structure: Garage

Excellent **Secondary Condition:**

Secondary Integrity: Good

Alterations:

Siding added (currently being removed)

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Queen Anne

Building Form: -No. of Stories: 2

Current Wall Materials: Aluminum

Original Wall Materials: Wood clapboard

Ornamentation: Flared walls; shingles in gables

Storefront Materials:

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation:

Foundation Material: Stone

Porch Type: Wrap around

Door Detailing: Casing

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Wood

Window Detailing: Casing

Significant Features:

Classical porch; window bay; leaded glass



2015

HISTORICAL RESEARCH

Original Owner: Isaac & Mary Nichols

Historic Name: Nichols House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

Likely built just after 1900. The original owners are reportedly Isaac & Mary Nichols, who moved here between 1900 & 1910. Isaac was a prominent Chicago jeweler. The house remained in the family through the 1920s. The concrete walk is stamped "Nichols."

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



Figure 2



Figure 3



Figure 4 Historic view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 348

Former Street Number: -

Street: South Craig Place

PIN Number: 06-08-302-021

Construction Date (s): 1925

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Good

Alterations:

Aluminum soffits		

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1

Current Wall Materials: Wood shingles

Original Wall Materials: Wood shingles

Ornamentation: Stonework; brackets

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: Brackets

Foundation Material: Stone

Porch Type: Entry

Door Detailing: -

Window Type: Casement

Window Configuration: Banded

Window Material: Wood

Window Detailing: Casing

Significant Features:

Stone chimney and porch



2015

HISTORICAL RESEARCH

Original Owner: Probably Edward H. Karp

Historic Name: -

Current Name: -

Original Architect: Harris Brothers E-1033

Alternate Architect: -

Original Contractor: Edward H. Karp (attributed)

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

The house may have been built about 1925. It was design E-1033 of the Harris Brothers Company Catalog of Homes.

Edward H. & Minnie Karp were owners in 1928 and he was a builder. He may have built the home. They lived there through 1940.



Figure 2



Figure 3 View of Harris Brothers catalog E-1033 courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 705

Former Street Number:

Street: **East Division Street**

PIN Number: 06-08-407-046

Construction Date (s): 1928

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Good

Alterations:

Windows replaced; door replaced

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: English Tudor

Building Form: Cottage No. of Stories:

Current Wall Materials: Stucco

Original Wall Materials: Stucco

Trim and stucco details **Ornamentation:**

Storefront Materials:

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: Curved eaves

Foundation Material:

Porch Type: Stoop

Door Detailing: Wood trim & casing

Window Type: Double hung 6/6

Window Configuration: Single; grouped

Window Material: Vinyl

Window Detailing: Wood trim & casing

Significant Features:

Stone chimney; curved eaves, stucco trim



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: Edwin Chase & Co.

Construction Cost: -

Permit: -

Subdivision: Lilac Lodge

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

More research is needed.

John & Edith Garrett lived here in 1938.

William & Blanche Westenberg rented here in 1939 through at least 1940.

Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 745

Former Street Number:

Street: **East Division Street**

PIN Number: 06-08-408-022

Construction Date (s): 1928

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Excellent **Secondary Condition:**

Secondary Integrity: Poor

Alterations:

Synthetic siding and eaves; windows replaced; bay

windows added

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Colonial

Building Form: Center hall No. of Stories:

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation:

Storefront Materials:

Roof Type: Side gable Materials: Asphalt shingle

Roof Ornamentation: Dormers

Foundation Material: Concrete

Porch Type: Stoop

Door Detailing: Sidelights

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Vinyl

Window Detailing:

Significant Features:

Entry canopy; dormers



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: Edwin Chase & Co.

Construction Cost: -

Permit: -

Subdivision: Lilac Lodge

Research & Archival Sources:

Limited file at Lombard Historical Society; www.ancestry.com

NOTES

More research is needed.

Daniel & Ann Creedon lived here in 1931 but not in 1930. They may have rented.

William & Mary Thumm owned the house from at least 1935 through 1940.



Figure 2



Figure 3 Historic view courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 414

Former Street Number: -

Street: South Garfield Terrace

PIN Number: 06-08-306-018

Construction Date (s): C. 1915

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Poor

Alterations:

Replacement windows		

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Prairie

Building Form: L Shape **No. of Stories:** 2

Current Wall Materials: Stucco

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: CMU

Porch Type: Entry

Door Detailing: -

Window Type: Double hung 1/1; casement

Window Configuration: Paired

Window Material: Wood

Window Detailing: Casing

Significant Features:

Cellar entry on side; trellis porch



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

Further research is needed on the date of construction and original owner. The house does appear in the 1925 Sanborn Fire Insurance map.

Aldo & Mary Allegretti were the owners in 1928 until 1931. He was an electrical engineer & Italian immigrant. They were not the original owners. It went through a series of owners in the 1930s & '40s. In 1949, William Robinson & family lived here & remained until 1962.



Figure 2



Figure 3 Circa 1950s view courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 617

Former Street Number:

Street: South Hammerschmidt Avenue

PIN Number: 06-17-109-003

Construction Date (s): c. 1928

Current Function: William Hammerschmidt School

Historic Function: School

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Poor

Secondary Structure:

Secondary Condition:

Secondary Integrity:

Alterations:

Additions at the front and side; windows replaced; overall

character altered

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Tudor Revival; Post Modern

Building Form: -No. of Stories:

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: Stone details

Storefront Materials:

Roof Type: Flat Materials: -

Roof Ornamentation: Parapet

Foundation Material: Concrete

Porch Type:

Door Detailing:

Window Type: Hopper

Window Configuration: Grouped

Window Material: Aluminum

Window Detailing:

Significant Features:



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: Hammerschmidt School

Current Name: William Hammerschmidt School

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

The Hammerschmidt School has been a fixture in Lombard since at least 1928 & has been enlarged well beyond its original design & footprint.

Figure 2



Figure 3



Figure 4 Historic view courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 54

Former Street Number: -

Street: South Highland Avenue

PIN Number: 06-09-103-072

Construction Date (s): c. 1863, rebuilt c. 1930

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Poor

Secondary Integrity: Poor

Alterations:

Shutters added; concrete stoop added

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: - No. of Stories: 2

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: -

Storefront Materials: -

Roof Type: Side gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: Concrete

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 3/1

Window Configuration: Paired

Window Material: Wood

Window Detailing: -

Significant Features:



2015

HISTORICAL RESEARCH

Original Owner:

Historic Name: Joseph & Catherine Reis House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society; www.ancestry.com

NOTES

There is limited research on this house but it reportedly dates from about 1863. About 1900, it was owned by Joseph & Catherine Reis. Joseph was a civil servant & died in 1931. His son Joseph Jr., a doctor with his own practice, lived here after 1931 with his wife Clara. Its form has a vernacular farmhouse character but it is clad in 20th century brick & windows. Joseph Jr. may have remodeled it about the time they moved in.

Although attributed as the Lewis farmhouse, more research is needed to verify.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



Figure 2



Figure 3



2015

GENERAL INFORMATION

Street Number: 426

Former Street Number: -

Street: South Highland Avenue

PIN Number: 06-09-305-016

Construction Date (s): 1924

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Poor

Alterations:

Synthetic siding and eaves; porch steps replaced; porch windows replaced; brackets wrapped in aluminum

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: Eave brackets

Storefront Materials: -

Roof Type: Front gable Materials: Asphalt shingle

Roof Ornamentation: Brackets

Foundation Material: CMU

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 4/1

Window Configuration: Single

Window Material: Wood

Window Detailing: Casing

Significant Features:

Brackets				



2015

HISTORICAL RESEARCH

Original Owner: Possibly Oscar & Ida Anderson

Historic Name: -

Current Name: -

Original Architect: Harris Brothers E-1018

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

Design is the E-1018 from "Harris Brothers Company Catalog of Homes." Oscar & Ida Anderson may have been the original owners.

Walter H. Meyer purchased in1938. By 1940, Otta Kautt & his family had moved in.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



Figure 2



Figure 3



Figure 4 Historic view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 324

Former Street Number: -

Street: South Lodge Lane

PIN Number: 06-08-404-033

Construction Date (s): 1928

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Synthetic siding and eaves; porch steps replaced; rear addition; porch enclosed; some windows replaced

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Dutch Colonial

Building Form: - No. of Stories: 2

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Gambrel Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: -

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 6/1

Window Configuration: Single

Window Material: Wood; vinyl

Window Detailing: -

Significant Features:

Gambrel roof



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: Albert Mumm (attributed)

Alternate Contractor: -

Developer: Edwin Chase & Co.

Construction Cost: -

Permit: -

Subdivision: Lilac Lodge

Research & Archival Sources:

Limited file at Lombard Historical Society; www.ancestry.com

NOTES

More research is needed.

Albert Mumm may have been the builder.

Robert Mather was a renter here with his wife Edna & family from about 1935 through at least 1940.



Figure 2



Figure 3 1961 View courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 401

Former Street Number: -

Street: South Lodge Lane

PIN Number: 06-08-407-012

Construction Date (s): 1927

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Excellent

Alterations:

Aluminum eaves; porch enclosed; porch stairs replaced; balustrade added above porch

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: - No. of Stories: 2

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: Stone details; brick bands

Storefront Materials: -

Roof Type: Hip Materials: Concrete tile

Roof Ornamentation: -

Foundation Material: Brick

Porch Type: Partial front

Door Detailing: -

Window Type: Double hung 6/6

Window Configuration: Single

Window Material: Wood

Window Detailing: Awnings

Significant Features:

Porch and roof



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: Edwin Chase & Co.

Construction Cost: -

Permit: -

Subdivision: Lilac Lodge

Research & Archival Sources:

No file at Lombard Historical Society; www.ancestry.com

NOTES

More research is needed.

Robert Walker lived here as a renter with his wife Muriel & family in 1940. They had moved in after 1935.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 400

Former Street Number: -

Street: South Lombard Avenue

PIN Number: 06-08-310-015 & 029

Construction Date (s): 1907

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Poor

Alterations:

Rear addition		

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Queen Anne

Building Form: - No. of Stories: 2

Current Wall Materials: Wood clapboard

Original Wall Materials: Wood clapboard

Ornamentation: Gable vergeboard; classical porch

Storefront Materials: -

Roof Type: Cross gable Materials: Wood-asphalt shingle

Roof Ornamentation: Vergeboard

Foundation Material: Stone

Porch Type: Wrap around

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Paired

Window Material: Wood

Window Detailing: Casing

Significant Features:

Bay window; porch; oval window; ornamental gables;

leaded glass



2015

HISTORICAL RESEARCH

Original Owner: Gustave & Augusta Shalk

Historic Name: Shalk House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

The house was built for Gustave & Augusta Shalk. They were married moved to Lombard & had this house built by 1907. They sold the house in 1925 to John & Elizabeth Pherigo. The Shalk's daughter & son-in-law, Ella & Alfred Olson lived next door at 401 S. Lombard.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



Figure 2



Figure 3



Figure 4 Historic view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 401

Former Street Number: -

Street: South Lombard Street

PIN Number: 06-08-311-028

Construction Date (s): 1924

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Poor

Alterations:

Siding added; aluminum eaves; compatible rear addition

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: Porch piers

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: CMU

Porch Type: Side partial

Door Detailing: Sidelights

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Wood

Window Detailing: Casing

Significant Features:

Fnc	hazanl	norch



2015

HISTORICAL RESEARCH

Original Owner: Likely Alfred & Ella Olson

Historic Name: Olson House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

www.ancestry.com

NOTES

Alfred & Ella Olson owned the house in 1930 through at least 1940 & may have been the original owners. He was a machinist from Sweden. Ella's parents, Gustave & Augusta Shalk, lived next door at 400 S. Lombard. Augusta was living with the family in 1940.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 421

Former Street Number: -

Street: South Lombard Avenue

PIN Number: 06-08-311-005

Construction Date (s): 1922

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: -

Secondary Condition: -

Secondary Integrity: -

Alterations:

Aluminum siding added

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1 1/2

Current Wall Materials: Aluminum

Original Wall Materials: Wood clapboard

Ornamentation: Brackets; rafter tails; porch piers

Storefront Materials: -

Roof Type: Side gable Materials: Asphalt shingle

Roof Ornamentation: Brackets & rafter tails

Foundation Material: CMU

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 9/1

Window Configuration: Paired

Window Material: Wood

Window Detailing: Casing

Significant Features:

Porch with cutout rails and decorative piers



2015

HISTORICAL RESEARCH

Original Owner: Darius & Marie Barta

Historic Name: Darius & Marie Barta House

Current Name: -

Original Architect: Sears Honor Bilt Home #3049

Alternate Architect: -

Original Contractor: Nels Bergman (attributed)

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

Built as a kit house from Sears Honor Bilt Home #3049. There are original blueprints & markings on framing boards.

Nels Bergman may have built the home. The original owners were Darius & Marie Barta. Darius was a civil engineer; Marie supervised a canning drive during the Depression & was active in the community. The family was living here through at least 1940.



Figure 2



Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 331

Former Street Number:

Street: West Madison Street

PIN Number: 06-18-200-010 & 011

Construction Date (s): 1930

Current Function: College Preparatory School

Historic Function: Green Valley School

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Condition:

Secondary Integrity:

Alterations:

Windows replaced; rear and side additions; original parapet details lost

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Tudor Revival

Building Form: -No. of Stories: 2

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: Stone window surrounds

Storefront Materials:

Roof Type: Flat Materials: -

Roof Ornamentation:

Foundation Material: Stone

Porch Type:

Door Detailing: Arched transom

Window Type: Double hung 1/1

Window Configuration: Grouped

Window Material: Aluminum

Window Detailing: Stone surrounds

Significant Features:

Arched	entry
--------	-------



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: Green Valley School

Current Name: College Preparatory School of America

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES



SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



Figure 2



Figure 3




Figure 4 Historical view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 127

Former Street Number: -

Street: North Main Street

PIN Number: 06-05-317-003

Construction Date (s): 1908

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Shutters added; aluminum eaves and trim added; $% \label{eq:continuous} % \la$

windows replaced

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Prairie Style

Building Form: Foursquare **No. of Stories:** 2

Current Wall Materials: Wood clapboard

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Hip Materials: Asphalt shingle

Roof Ornamentation: Dormers

Foundation Material: CMU

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Vinyl

Window Detailing: -

Significant Features:



2015

HISTORICAL RESEARCH

Original Owner: Stella Manning

Historic Name: Dwight & Clarissa Cochran House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: Samuel Lumbard

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

The house was apparently built for Stella Manning, who lived here in 1910 with her father James Webb & her daughter Clarissa & her husband Dwight Cochran. Dwight & Clarissa Cochran later inherited the house (Stella died after 1920). Dwight was the son of James Ira Cochran, who lived at 225 Main. Clarissa's family also lived nearby along Main: brother Claude & family at 131 as well as several Webbs nearby. Dwight worked at the meatpackers Swift & Co. & lived in the house past 1930.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 14, 2015



2015

GENERAL INFORMATION

Street Number: 131

Former Street Number: -

Street: North Main Street

PIN Number: 06-05-317-002

Construction Date (s): 1914

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Good

Alterations:

Shutters added; aluminum eaves added; windows replaced; dormer window altered; rear deck added

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Prairie

Building Form: Foursquare **No. of Stories:** 2

Current Wall Materials: Wood clapboard; stucco

Original Wall Materials: Wood clapboard; stucco

Ornamentation: Geometric piers

Storefront Materials: -

Roof Type: Hip Materials: Asphalt shingle

Roof Ornamentation: Deep eaves; dormer

Foundation Material: CMU

Porch Type: Full front

Door Detailing: -

Window Type: Double hung (multi-pane)

Window Configuration: Single

Window Material: Vinyl

Window Detailing: -

Significant Features:

Porch	piers



2015

HISTORICAL RESEARCH

Original Owner: Claude & Ada Manning (rented)

Historic Name: Claude & Ada Manning House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: Samuel Lumbard

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

The house was rented by Claude & Ada Manning. Claude died in 1922 and his widow remained in the house until the early 1930s. Ada was Superintendant of the Lombard Schools in the late 1920s & a founder of Lambda State of the Delta Kappa Gamma Society (an organization of women educators).

Claude's sister, Clarissa & her husband Dwight Cochran lived next door at 127 N. Main.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 14, 2015



2015

GENERAL INFORMATION

Street Number: 211

Former Street Number:

Street: North Main Street

PIN Number: 06-05-307-031 & 041

Construction Date (s): 1919

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Excellent **Secondary Condition:**

Secondary Integrity: Poor

Alterations:

Side porch enclosed or added; aluminum eaves added; synthetic siding on dormers; clad with brick historically

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Colonial Revival

Building Form: -No. of Stories: 2

Current Wall Materials: Brick

Original Wall Materials: Wood clapboard

Ornamentation: Classical portico; keystones

Storefront Materials:

Roof Type: Side gable Materials: Asphalt shingle

Roof Ornamentation: Dormers

Foundation Material: Concrete

Porch Type: Portico

Door Detailing: Fan & sidelights

Window Type: Double hung 8/1

Window Configuration: Single

Window Material: Wood

Window Detailing:

Significant Features:

Classical portico



2015

HISTORICAL RESEARCH

Original Owner: Danford & Irene Abrams

Historic Name: Rayfero

Current Name: aka Spalding House

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; ancestry.com

NOTES

The house was likely built in 1919 with clapboard siding. It was owned by Danford & Irene Abrams. Danford was a wealthy businessman & owned the Lombard Floral Co. from 1917-22. This seems to be about the extent of time they lived in Lombard. He was also a stockholder in the Lombard State Bank. Irene was active in social organizations like the Chicago Women's Club. RayFero was the name given by the Abrams.

The Abrams sold it to Roy & Ethel Spalding in 1923. The Spaldings owned it until the mid-1950s. It is likely that the house was clad with stucco & then brick by the Spaldings or shortly thereafter.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 14, 2015



Figure 2 Historic view courtesy of Lombard Historical Society



Figure 3



2015

GENERAL INFORMATION

Street Number: 472

Former Street Number: -

Street: North Main Street

PIN Number: 06-06-218-021

Construction Date (s): 1935

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Good

Secondary Structure: Attached garage

Secondary Condition: -

Secondary Integrity: Good

Alterations:

Synthetic siding; windows replaced

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: - No. of Stories: 1

Current Wall Materials: Vinyl

Original Wall Materials: -

Ornamentation: -

Storefront Materials: -

Roof Type: Flat Materials: -

Roof Ornamentation: -

Foundation Material: Concrete

Porch Type: Inset alcove

Door Detailing: -

Window Type: Palladian

Window Configuration: Single

Window Material: Vinyl

Window Detailing: -

Arch	ed	ent	rv



2015

HISTORICAL RESEARCH

Original Owner: Jessie & Marion Baker

Historic Name: Baker House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: Home Builders Company

Alternate Contractor: -

Developer: -

Construction Cost: \$7,500

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

The house appears to have been built for or bought by Jessie & Marion Baker in 1935. The Baker family lived there at least through 1940. Jessie was a bartender.

Nothing is currently known about the design of the house. 466 N. Main was built at the same time by the same builder. It is a similar design but in brick.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 502

Former Street Number: -

Street: North Main Street

PIN Number: 06-06-215-023

Construction Date (s): c. 1931

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Attached garage

Secondary Condition: -

Secondary Integrity: Poor

Alterations:

Large rear addition; windows replaced; shutters replaced


SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Colonial Revival

Building Form: Gable front **No. of Stories:** 2

Current Wall Materials: Wood clapboard

Original Wall Materials: Wood clapboard

Ornamentation: Half round window

Storefront Materials: -

Roof Type: Front gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: Concrete

Porch Type: Wrap around

Door Detailing: -

Window Type: Double hung 6/1

Window Configuration: Single

Window Material: Vinyl

Window Detailing: Surrounds

Significant Features:

Special wood siding; half round window in gable



2015

HISTORICAL RESEARCH

Original Owner: Dewey & Marion Johnson

Historic Name: Johnson House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society; www.ancestry.com

NOTES

The house seems to have been built about 1931. Dewey & Marion Johnson were living there by 1935 & may have been the original owners. Dewey was a research engineer.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



Figure 2



Figure 3



Figure 4 Historic view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 566

Former Street Number: -

Street: South Main Street

PIN Number: 06-07-413-036

Construction Date (s): c. 1847

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Synthetic siding; windows replaced; rear and side addition; shutters added; wing and entry altered from original upright and wing configuration

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: Upright & wing No. of Stories: 2

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: -

Porch Type: Stoop

Door Detailing: -

Window Type: Double hung 4/4

Window Configuration: Single

Window Material: Vinyl

Window Detailing: -

Wind	ow l	hav
VVIIIU	OVV	vay



2015

HISTORICAL RESEARCH

Original Owner: Probably Adam & Katharina Glos

Historic Name: Glos Farmhouse

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: Green Valley

Research & Archival Sources:

Extensive file at Lombard Historical Society; www.ancestry.com

NOTES

The house appears to be a modified upright & wing farmhouse that may dates to 1847. It is located on the land owned & farmed by Adam Glos as early as 1850. Adam & Katharina were married in 1847 & may have built the house then. Gloss died in 1907.

Fred Birr reportedly lived in the house as a child in the 1880s. The Birrs rented the house from the Glos family and worked the farm.

Charles Cress & Viktor Hoyer bought the house & land from the Glos family and developed the Green Valley Subdivision.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



Figure 2

Figure 3



2015

GENERAL INFORMATION

Street Number: 640

Former Street Number: -

Street: South Main Street

PIN Number: 06-18-203-030

Construction Date (s): c. 1930

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Synthetic siding; windows replaced

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Colonial Revival

Building Form: Bungalow **No. of Stories:** 1

Current Wall Materials: Aluminum

Original Wall Materials: Wood clapboard

Ornamentation: Classical portico

Storefront Materials: -

Roof Type: Side gable **Materials:** Asphalt shingle

Roof Ornamentation: -

Foundation Material: Concrete

Porch Type: Portico

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Paired

Window Material: Vinyl

Window Detailing: Casing

	portico



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: Montgomery Ward "Potomac"

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

House is a kit built house - the Montgomery Ward & Company "Potomac" model.

More research is needed on the original owner.

The "Potomac"—A Quaint Colonial Bungalow

5 Boss and Bos

Flore Includes

Flor

Figure 2 Ad for Montgomery Ward "Potomac" kit house courtesy of Lombard Historical Society

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 322

Former Street Number: -

Street: West Maple Street

PIN Number: -

Construction Date (s): 1912

Current Function: Sacred Heart School

Historic Function: School

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: -

Secondary Condition: -

Secondary Integrity: -

Alterations:

Side additions; windows replaced; doors replaced

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: 20th Century Commercial

Building Form: - No. of Stories: 2

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: Stone trim; brick patterns; cornice

Storefront Materials: -

Roof Type: Flat Materials: -

Roof Ornamentation: Copper cornice; parapet

Foundation Material: Concrete

Porch Type: Stoop

Door Detailing: Arched

Window Type: Double hung with transom 1/1

Window Configuration: Grouped

Window Material: Aluminum

Window Detailing: Stone sills

Arc	hed	entry
-----	-----	-------



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: Sacred Heart School

Current Name: Sacred Heart School

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

Sacred Heart School was built in 1912 to serve elementary education for Lombard's Catholic community. It has been expanded several times over the years.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 14, 2015



Figure 2



Figure 3



Figure 4 Historic view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 143

Former Street Number: -

Street: South Martha Street

PIN Number: 06-08-114-012

Construction Date (s): c. 1925

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Aluminum eaves; shutters added; porch enclosed

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Chicago bungalow **No. of Stories:** 1 1/2

Current Wall Materials: Stucco

Original Wall Materials: Stucco

Ornamentation: Brackets; brick details on piers

Storefront Materials: -

Roof Type: Front gable Materials: Asphalt shingle

Roof Ornamentation: Brackets

Foundation Material: Brick

Porch Type: Stoop; partial front

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Paired

Window Material: Wood

Window Detailing: Brick sills

Porch			



2015

HISTORICAL RESEARCH

Original Owner: Probably Peter & Jessie Mayer

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

House was built by 1928 and was owned at that time by the Mayer family. Peter Mayer was a descendent of the Churchill family, original pioneers of Babcock's Grove (Lombard).



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 157

Former Street Number: -

Street: South Martha Street

PIN Number: 06-08-114-015

Construction Date (s): 1913

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Rear addition; synthetic siding and eaves; shutters added;

windows replaced

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1 1/2

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Side gable Materials: Asphalt shingle

Roof Ornamentation: Shed dormer

Foundation Material: CMU

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Vinyl

Window Detailing: -



2015

HISTORICAL RESEARCH

Original Owner: Samuel & Zada Wright

Historic Name: Wright House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

House was built for Samuel & Zada Wright. They lived here with their family at least into the 1940s. Samuel owned the Wright & Huber Printing Co. Zada was the daughter of Allen Hills, a founder of Lombard.

Suffered a fire c. 1975.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 175

Former Street Number:

Street: South Martha Street

PIN Number: 06-08-114-053

Construction Date (s): 1904

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Excellent **Secondary Condition:**

Secondary Integrity: Poor

Alterations:

Siding added; eaves covered; porch likely rebuilt; shutters

added

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style:

Building Form: L Shape No. of Stories: 2

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation:

Storefront Materials:

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation:

Foundation Material: Stone

Porch Type: Wrap around

Door Detailing: Transom

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Wood

Window Detailing: Casing

Significant Features:

Palladian gable window



2015

HISTORICAL RESEARCH

Original Owner: William & Johanna Campbell

Historic Name: Campbell House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: Charles Assman

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Extensive file at Lombard Historical Society; www.ancestry.com

NOTES

William & Johanna Campbell had this house built in 1904 by Charles Assman. William was a salesman with a chemical company. There are some records of the construction in the Lombard Historical Society files. Johanna continued to live in the house after William's death in 1927.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: September 17, 2015



2015

GENERAL INFORMATION

Street Number: 565

Former Street Number: -

Street: South Martha Street

PIN Number: 06-08-321-004

Construction Date (s): 1949

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Aluminum eaves; door replaced; windows replaced

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Mid-Century Modern

Building Form: Ranch No. of Stories: 1

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: Concrete quoins

Storefront Materials: -

Roof Type: Flat Materials: -

Roof Ornamentation: Angled eaves

Foundation Material: Brick

Porch Type: Stoop

Door Detailing: Quoins

Window Type: Sliders

Window Configuration: Banded

Window Material: Clad

Window Detailing: -

Significant Features:

Butterfly roof; prominent chimney



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

More research is needed.



Figure 2



Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 48

Former Street Number:

Street: **Orchard Terrace**

PIN Number: 06-07-204-037

Construction Date (s): 1929

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Excellent **Secondary Condition:**

Secondary Integrity: Good

Alterations:

Garage may be original; some windows replaced

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Tudor Revival

Building Form: -No. of Stories: 2

Current Wall Materials: Brick, stucco, wood shingle, stone

Original Wall Materials: Brick, stucco, wood shingle, stone

Ornamentation: Half timbering, stone arch

Storefront Materials:

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: Steeply pitched gable

Foundation Material: Brick

Porch Type: Stoop

Door Detailing: Arched

Window Type: Double hung 1/2

Window Configuration: Single and paired

Window Material: Wood

Window Detailing: Some diamond panes

Significant Features:

Arched entry, steeply pitched roof



2015

HISTORICAL RESEARCH

Original Owner:	Samuel & Sarah Truby
Historic Name:	Truby House
Current Name:	-
Original Architect:	-
Alternate Architect:	-
Original Contractor:	-
Alternate Contractor:	-
Developer:	Figure 2

Research & Archival Sources:

Construction Cost:

File at Lombard Historical Society

NOTES

Permit:

Subdivision:

The house was rented by Samuel & Sarah Truby, who were retired & living in the house in 1930 with their daughter Estella. Samuel died in 1933 & Estella rented the house to the Edward Wigand family. It appears that Estella owned the house & had bought it for her parents to retire in.

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 14, 2015



2015

GENERAL INFORMATION

Street Number: 455

Former Street Number: -

Street: West St. Charles Road

PIN Number: 06-07-105-035 & 050

Construction Date (s): 1910

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: -

Secondary Condition: -

Secondary Integrity: -

Alterations:

Shutters added; rear addition

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: Yes LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: Foursquare **No. of Stories:** 2

Current Wall Materials: Wood clapboard

Original Wall Materials: Wood clapboard

Ornamentation: Classical porch columns

Storefront Materials: -

Roof Type: Hip Materials: Asphalt shingle

Roof Ornamentation: Dormer

Foundation Material: CMU

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Wood

Window Detailing: Casing, some leaded glass

Porch			



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: aka Roy & Evelyn Miller House

Original Architect: -

Alternate Architect: -

Original Contractor: Attributed to Seikman

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

Roy & Evelyn Miller moved to the house with their family in 1922. They had been living in Oak Park. The family lived there at least until 1930. Roy was an engineer with Bell Telephone.

Reportedly a man named Seikman had the house built along with 448 St. Charles Road. Who lived there originally is not known.



Figure 2 Image courtesy of Lombard Historical Society

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 14, 2015



2015

GENERAL INFORMATION

Street Number: 523

Former Street Number: -

Street: East Washington Boulevard

PIN Number: 06-08-411-006

Construction Date (s): 1923

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Poor

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Synthetic siding and eaves; stoop replaced; windows replaced; porch infilled; rear addition; shutters added

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: Bungalow **No. of Stories:** 1

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Hip Materials: Asphalt shingle

Roof Ornamentation: Dormer

Foundation Material: CMU

Porch Type: Stoop

Door Detailing: -

Window Type: Casement; double hung 1/1

Window Configuration: Paired

Window Material: Vinyl

Window Detailing: -

l		



2015

HISTORICAL RESEARCH

Original Owner: Joseph & Frances Schmidt

Historic Name: Schmidt House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited File at Lombard Historical Society

NOTES

This is reportedly a Harris Brothers Company kit designed house but no documentation is on file at this time.

The original owners appear to be Joseph & Frances Schmidt. Joseph worked at Florsheim Shoes. They were married in 1920 & may have moved to Lombard shortly thereafter to raise their family.

Albert & Emily Youhanna moved in about 1934.



Figure 2



Figure 3 Historic view courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 1005

Former Street Number: -

Street: East Washington Boulevard

PIN Number: 06-09-316-001

Construction Date (s): 1914

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Condition: Excellent

Secondary Integrity: Poor

Alterations:

Synthetic siding; porch enclosed; porch stoop added

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1 1/2

Current Wall Materials: Plywood & clapboard

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Side gable **Materials:** Asphalt shingle

Roof Ornamentation: -

Foundation Material: -

Porch Type: Full front

Door Detailing: -

Window Type: Double hung 3/1

Window Configuration: Banded

Window Material: Wood

Window Detailing: Casing

Dormer		



2015

HISTORICAL RESEARCH

Original Owner: Perry & Marian Sears

Historic Name: Perry & Marian Sears House

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

The house was owned for many years by Perry & Marian Sears. Perry's brother Frank lived next door. They both worked for the Chicago Surface Lines. Their daughter Priscilla lived in the house in the 1940s.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 100

Former Street Number:

Street: West Washington Boulevard

PIN Number: 06-07-405-083

Construction Date (s): 1947

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Attached garage

Secondary Condition:

Secondary Integrity: Poor

Alterations:

Synthetic siding added; windows replaced; garage significantly altered


SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark: No





ARCHITECTURAL DESCRIPTIONS

Architectural Style:

Building Form: Ranch No. of Stories:

Current Wall Materials: Vinyl

Original Wall Materials: -

Ornamentation: Stonework

Storefront Materials:

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation:

Foundation Material: Concrete

Porch Type: Terrace

Door Detailing:

Window Type: Casement; fixed

Window Configuration: Paired; banded

Window Material: Vinyl

Window Detailing:

Significant Features:

Stone planter and chimney



2015

HISTORICAL RESEARCH

Original Owner: James E. McDaniel

Historic Name: James E. McDaniel House

Current Name: aka Tribune Prize Home

Original Architect: W.R. Burns, Jr.

Alternate Architect: -

Original Contractor: Green Valley Homes, Inc.

Alternate Contractor: -

Developer: Chicago Tribune Company

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

Designed & built as part of a Post-WWII initiative by the Chicago Tribune to identify the future of affordable housing called the Chicagoland Home Prize Competition. It was opened to the public for viewing in 1947 prior to being turned over for occupancy by a veteran & his family. Construction costs were donated by the contractor with design fees paid by the Tribune.

James E. McDaniel was provided with the house as part of the competition. He was a navy veteran.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



Figure 2



Figure 3



Figure 4 Historic image courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 111

Former Street Number:

Street: West Washington Boulevard

PIN Number: 06-07-409-012

Construction Date (s): 1947

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Poor

Secondary Structure: Attached garage

Secondary Condition:

Secondary Integrity: Good

Alterations:

Side addition; entry wing altered; synthetic siding;

windows replaced


SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Mid-Century Modern

Building Form: -No. of Stories: 1 1/2

Current Wall Materials: Cement Board

Original Wall Materials: Wood clapboard

Ornamentation:

Storefront Materials:

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation:

Foundation Material: Concrete

Porch Type: Terrace

Door Detailing:

Window Type: **Awning**

Window Configuration: Banded

Window Material: Clad

Window Detailing:

Significant Features:

Banded windows of rear 2-story wing



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: aka Tribune Prize Home

Original Architect: Custis Woolford, Jr.

Alternate Architect: Ralph DeLos Peterson, Jr.

Original Contractor: Green Valley Homes, Inc.

Alternate Contractor: -

Developer: Chicago Tribune Company

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Extensive file at Lombard Historical Society

NOTES

Designed & built as part of a Post-WWII initiative by the Chicago Tribune to identify the future of affordable housing called the Chicagoland Home Prize Competition. It was opened to the public for viewing in 1947 prior to being turned over for occupancy by a veteran & his family. Construction costs were donated by the contractor with design fees paid by the Tribune.

The original owner is not currently known.



Figure 2



Figure 3 Historic Image Courtesy Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 242

Former Street Number:

Street: West Washington Boulevard

PIN Number: 06-07-405-042

Construction Date (s): 1943

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Attached garage

Secondary Condition:

Secondary Integrity: Good

Alterations:

Garage altered; synthetic siding and eaves; windows replaced; door replaced; shutters added

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Mid-Century Modern

Building Form: Ranch No. of Stories:

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation:

Storefront Materials:

Roof Type: Shed Materials: -

Roof Ornamentation: Deep eaves

Foundation Material: Concrete

Porch Type: Stoop

Door Detailing:

Window Type: Double hung 1/1; sliders

Window Configuration: Banded

Window Material: Vinyl

Window Detailing: Casing

Significant Features:

Dramatically sloped roof



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: -

Current Name: -

Original Architect: Attributed to George Keck

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

Reportedly built as a University of Illinois "Solar House." George Keck, a pioneer architect with solar homes, reportedly designed it. Keck is best known for his house design at the 1933 Chicago World's Fair. More research is needed.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: August 25, 2015



2015

GENERAL INFORMATION

Street Number: 47

Former Street Number: -

Street: South Westmore Avenue

PIN Number: 06-09-107-001

Construction Date (s): 1911

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Excellent

Secondary Structure: Coach house

Secondary Condition: Poor

Secondary Integrity: Good

Alterations:

Rear porch enclosed

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: Yes

National Register Criterion: C

LHS Plaque: No LHC Landmark: No

Reason for Significance:

Excellent example of a high-end Craftsman style bungalow on a larger estate with intact landscape design



ARCHITECTURAL DESCRIPTIONS

Architectural Style: Craftsman

Building Form: Bungalow **No. of Stories:** 1

Current Wall Materials: Stucco

Original Wall Materials: Stucco

Ornamentation: Eave brackets

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: Eave brackets

Foundation Material: CMU

Porch Type: -

Door Detailing: -

Window Type: Double hung 3/1

Window Configuration: Banded

Window Material: Wood

Window Detailing: Casing

Significant Features:

Iron fence; yard trellis; gate



2015

HISTORICAL RESEARCH

Original Owner: Susannah Batty

Historic Name: Susannah Batty House

Current Name: aka Beatty House

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Extensive file at Lombard Historical Society; www.ancestry.com

NOTES

The house was built for Susannah Batty in 1911. She was a widow & her son Harry (Beatty) reportedly had it built for her. Though the property was purchased in 1909, the Batty family were all living in Chicago in 1910. Her husband died shortly thereafter.

Charles & Ida Hagge lived in the house after Susannah's death in 1928. Ida was her daughter & Charles was a transit motorman. In the mid and late '30s, the family transferred ownership several times.

Harry Beatty (son) was a prominent figure & technical director in the Chicago Civic Opera House. He reportedly entertained Opera figures at the house & gardens in the '20s.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



Figure 2



Figure 3



Figure 4



2015

GENERAL INFORMATION

Street Number: 247

Former Street Number: -

Street: South Westmore Avenue

PIN Number: 06-09-114-033

Construction Date (s): c. 1911

Current Function: Commercial & Residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Poor

Secondary Structure: -

Secondary Condition: -

Secondary Integrity: -

Alterations:

Synthetic siding; stoop added; windows replaced; rear addition; dormers added; storefront enclosed/altered

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: Gable front cottage **No. of Stories:** 1 1/2

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Front gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: CMU

Porch Type: Concrete stoop

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Paired

Window Material: Vinyl

Window Detailing: -

1			
1			
1			
1			



2015

HISTORICAL RESEARCH

Original Owner: -

Historic Name: Moritz Golterman Grocery

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

The building may have been built in 1911 and was a combination of shop & residence. Early records are not complete but it was Moritz Golterman's Grocery in 1920; Boulger's Delicatessen in 1928 and Westmore Delicatessen in 1931 until at least '38.

Moritz was a descendent of the Golterman family, pioneers of York Center.



Figure 2



Figure 3 Older view courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

1869				
GENERAL INFORMATION	DN			
Street Number:	300			
Former Street Number:	-			
Street:	South Westmore Avenue			
PIN Number:	06-09-303-006			
Construction Date (s):	1926			
Current Function:	Commercial			
Historic Function:	Commercial			
PHYSICAL EVALUATION	N			
Condition:	Good			
Integrity:	Excellent			
Secondary Structure:	-			
Secondary Condition:	-			
Secondary Integrity:	-			
Alterations:				
SIGNIFICANCE				
Landmark/National Regis	ster: No			
National Register Eligible: No				
National Register Criterio	on:			
LHS Plaque: No	LHC Landmark: No			
Reason for Significance:				



ARCHITECTURAL DESCRIPTIONS

Architectural Style:	20th Century Comn	nercia
----------------------	-------------------	--------

Building Form: 1 Part commercial **No. of Stories:** 1

Current Wall Materials: Brick

Original Wall Materials: Brick

Ornamentation: Stone details

Storefront Materials: Copper window frames

Roof Type: Flat Materials: -

Roof Ornamentation: Parapet

Foundation Material: Brick

Porch Type: -

Door Detailing: Transom

Window Type: -

Window Configuration: -

Window Material: -

Window Detailing: -

()riginal	ctoratront
Onema	storefront



2015

HISTORICAL RESEARCH

Original Owner: Alfred & Anna Ciha

Historic Name: Ciha's Hardware

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society

NOTES

Alfred & Anna Ciha ran a hardware store here through at least 1940.

It was also reportedly a ticket office for the C.A. & E. Railroad which ran adjacent to the store.



Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 427

Former Street Number:

Street: South Westmore Avenue

PIN Number: 06-09-310-020

Construction Date (s): c. 1905

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Excellent **Secondary Condition:**

Secondary Integrity: Poor

Alterations:

Synthetic siding; windows replaced; entry altered; side addition; original porch removed; eaves altered

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plaque: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style:

Building Form: Gable front house **No. of Stories:**

Current Wall Materials: Vinyl

Original Wall Materials: Wood clapboard

Ornamentation:

Storefront Materials:

Roof Type: Front gable Materials: Asphalt shingle

Roof Ornamentation:

Foundation Material: Stone

Porch Type: Stoop

Door Detailing:

Window Type: Double hung 6/6

Window Configuration: Single

Window Material: Vinyl

Window Detailing:



2015

HISTORICAL RESEARCH

Original Owner: H.J. & Emma Meyer

Historic Name: Meyer's Farmhouse

Current Name: aka Sears Family House

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Extensive file at Lombard Historical Society; www.ancestry.com

NOTES

The house appears to have been built about 1904 but has been significantly altered. It was the farmhouse for the H.J. & Emma Meyer family. The Meyer family owned considerable farmland flanking Westmore south of the A.E. & C. tracks. H.J. died by 1910 though the family seems to have still been living in the house.

It was then owned by the Frank G. & Ruby Sears family for many decades.

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



Figure 2



Figure 3 Historical view courtesy of Lombard Historical Society



Figure Historical view courtesy of Lombard Historical Society



2015

GENERAL INFORMATION

Street Number: 528

Former Street Number: -

Street: South Westmore Avenue

PIN Number: 06-09-315-035

Construction Date (s): c. 1891 or c. 1914

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Good

Secondary Structure: Attached garage

Secondary Condition: -

Secondary Integrity: Poor

Alterations:

Windows replaced; porch enclosed; front garage added

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: -

Building Form: L Shape House **No. of Stories:** 2

Current Wall Materials: Wood clapboard

Original Wall Materials: Wood clapboard

Ornamentation: -

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: Stone

Porch Type: Wrap around

Door Detailing: -

Window Type: Double hung 1/1

Window Configuration: Single

Window Material: Vinyl

Window Detailing: Casing

l		



2015

HISTORICAL RESEARCH

Original Owner: August & Mary Ahrens

Historic Name: August & Mary Ahrens Farmhouse

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society; www.ancestry.com

NOTES

This house was reportedly built in 1891 for the Ahrens family farm. However, according to the 1904 York Township map, the Ahrens farm was further west of Westmore at that time (the Meyer's were neighbors). The county assessor lists the construction date as 1914. The Meyer family seems to have been selling off their farmland by then & it may date from that time.

August & Mary were married in 1889 & had a large family they raised for years in the house.



Figure 2



Figure 3 Historic view courtesy of Lombard Historical Society

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 581

Former Street Number: -

Street: South Westmore Avenue

PIN Number: 06-09-316-046

Construction Date (s): 1953

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Good

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Good

Alterations:

SIGNIFICANCE


Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Mid-Century Modern

Building Form: Ranch No. of Stories: 1

Current Wall Materials: Brick; stone

Original Wall Materials: Brick; stone

Ornamentation: Stone details

Storefront Materials: -

Roof Type: Angled flat Materials: -

Roof Ornamentation: Deep eaves

Foundation Material: Slab

Porch Type: -

Door Detailing: -

Window Type: Fixed

Window Configuration: Banded

Window Material: Wood

Window Detailing: Angled

Significant Features:

Angled wing walls; sloped roof



2015

HISTORICAL RESEARCH

Original Owner: Possibly Paul & Leta Jorgensen

Historic Name: -

Current Name: -

Original Architect: -

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

Limited file at Lombard Historical Society

NOTES

Further research is needed.

Figure 2

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015



2015

GENERAL INFORMATION

Street Number: 1123

Former Street Number: Park Avenue

Street: East Woodrow Avenue

PIN Number: 06-09-311-002

Construction Date (s): 1928

Current Function: Single family residential

Historic Function: Single family residential

PHYSICAL EVALUATION

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Condition: Good

Secondary Integrity: Good

Alterations:

Windows replaced; terrace railing added; shutters added

SIGNIFICANCE

Landmark/National Register: No

National Register Eligible: No

National Register Criterion:

LHS Plague: No LHC Landmark: No

Reason for Significance:





ARCHITECTURAL DESCRIPTIONS

Architectural Style: Tudor Revival

Building Form: Cottage **No. of Stories:** 1 1/2

Current Wall Materials: Wood shingles

Original Wall Materials: Wood shingles

Ornamentation: Stonework

Storefront Materials: -

Roof Type: Cross gable Materials: Asphalt shingle

Roof Ornamentation: -

Foundation Material: -

Porch Type: Terrace

Door Detailing: Arched

Window Type: Double hung 1/1

Window Configuration: Banded

Window Material: Vinyl

Window Detailing: -

Significant Features:

Entry; chimney



2015

HISTORICAL RESEARCH

Original Owner: Emil & Rena Besic

Historic Name: Besic House

Current Name: -

Original Architect: Sears Kit House "Mitchell"

Alternate Architect: -

Original Contractor: -

Alternate Contractor: -

Developer: -

Construction Cost: -

Permit: -

Subdivision: -

Research & Archival Sources:

File at Lombard Historical Society; www.ancestry.com

NOTES

This house was a Sears catalog kit house, the "Mitchell" model. There are Sears labels on some of the woodwork.

The house was built for Emil & Rena Besic & the family lived here until about 1934. Emil ran a bowling alley. The Besic's son, Ralph, was a prominent auctioneer.



Figure 2 Sears "Mitchell" catalog ad courtesy of Lombard Historical Society

Figure 3

SURVEY INFORMATION

Surveyor: Douglas Gilbert, AIA

Survey Date: July 17, 2015